20 Kg, tension & compression

FORCE GAUGE

Model: FG-5020 *ISO-9001, CE, IEC1010*



FEATURES

- * 20 Kg, Kg/LB/Newton.
- * Tension or Compression, Peak hold, Zero.
- * Positive/ Reverse display.
- * 5 digits LCD with back light.
- *RS-232 computer interface.
- * Full line accessories, optional test stand.
- * DC 1.5V battery (UM-3, AA) x 6 or DC 9V adapter in.





The Art of Measurement

FORCE GAUGE

Model: FG-5020

FEATURES

*	Large LCD display with back light.
*	20 Kg, wide capacity, high resolution, high accuracy,
	high repeatability.
*	3 kind display unit : g, oz, Newton.
*	Tension & compression capability .
*	Peak hold (Max. load) can be held in display during
	make tension or compression measurement.
*	Zero button can operate both for normal measuring
	& the " peak hold " operation.
*	Full capacity zero (tare) control capability.
*	Fast/Slow response time push button.
*	Positive or reverse display direction select.
*	Full line accessories (adapters) are included.
*	Hand held & stand mounted gauges are available.
*	Low power consumption gives long battery life.
*	Build in low battery indicator.
*	Microprocessor circuit & exclusive load cell transducer.
*	Over load protection.
*	RS-232 computer interface.
*	Built-in DC 9V power adapter input socket.
*	Professional test stand (optional).

SPECIFICATIONS

Display	LCD (Liquid crystal display).
	5 digits, 16 mm (0.63") digit size.
	Back light.
Display	Positive or Reverse direction, select by
Direction	the push button on the front panel.
Function	Tension & Compression (Push & Pull).
	Normal force, Peak hold (Max. load).
Peak hold	Will freeze the display value of the
	Peak load (Max. load).
Zero	Zero button can be operated both for
	"normal force" or "peak hold" operation
Unit select	g/oz/Newton
Measure	20.00 Kg/44.10 LB/196.10 Newton.
Capacity	
Resolution	0.01 Kg/0.01 LB/0.05Newton.
Min. Display	0.02 Kg/0.07 LB/0.3 Newton,
Accuracy	\pm (0.5 % + 2 digits), within 23 \pm 5°C.
	* Under the test weight on 10 Kg & 20 Kg.

Update time	Fast Approx. 0.2 second.
	Slow Approx. 0.6 second.
Over range	Display show " " when in over
Indicator	range status.
Data output	RS-232 serial computer interface.
Overload	Max. 30 kg.
Capacity	
Full Scale	Approx. 0.4 mm max.
Deflection	
Zero/tare	Max. full capacity.
Control	
Circuit	Exclusive microprocessor LSI-circuit.
Power Supply	6 x 1.5 V AA (UM-3) size battery
	or DC 9V adapter (not included).
Power	Approx. DC 28 mA
Consumption	
Transducer	Exclusive load cell.
Operating	0℃ to 50℃(32°F to 122°F).
Temperature	
Operating	Less than 80% RH.
Humidity	
Dimension	215 x 90 x 45 mm (8.5 x 3.5 x 1.8 inch).
Weight	650 g (1.43 LB)/with batteries.
Mounting	Main instrument with mounting holes are
Holes	provided on the back case, easy stand
	mounting.
Accessories	Operating manual1 PC.
Included	Flat-head adapter 1 PC.
	Hook adapter1 PC.
	Cone head adapter1 PC.
	Chisel head adapter 1 PC.
	120 mm extension rod1 PC.
	Carrying case1 PC.
Optional	* Test stand, Model : FS-1001
Accessories	* Wedge grip, Model : WG-01
	* RS232 cable, Model : UPCB-01
	* USB cable, Model : USB-01
	* Software for data logging & data
	recorder.
	Model: SW-U801-WIN.

 $^{^{\}star}$ Appearance and specifications listed in this brochure are subject to change without notice.

FORCE GAUGE

Model: FS-1001 *ISO-9001, CE, IEC1010*



FEATURES

* Optional; test stand, be connected with FG-5000A, FG-20KG, FG-5000A-232, FG-20KG-232, whole system will be a useful tool for material's tension and compression analysis.

* Size: 650 x 250 x 230 mm.





The Art of Measurement